

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 12

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 12

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 8			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 8			
Problem Identification & Resolution / IR			
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2009-008
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2009-003
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00412/2009-008
Number of Items for this Docket: 4			
Percent of Total for this Docket: 33			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00412/2009-008
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00412/2009-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2009-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00412/2009-003
Number of Items for this Docket: 6			
Percent of Total for this Docket: 50			
Total Items for this Docket: 12			
