

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 6
National Average: 46
2x National Average: 92
National Median: 23
Average for Selected Dockets: 6

Facility Name: Vermont Yankee Docket (050- 00271)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 17			
Procedures & Reference Document / IR			
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 17			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00271/2009-006
Number of Items for this Docket: 4			
Percent of Total for this Docket: 67			
Total Items for this Docket: 6			
