

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 27

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 27

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00334/2010-502
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00334/2010-004
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00334/2009-005
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00334/2010-004
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00334/2009-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 15			
Training / IR			
102 - Individual knowledge LTA	O - Operations	O - Control Room Ops	050-00334/2010-502
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00334/2009-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2010-502
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2009-005
186 - Failure to take action / meet requirements	P - Procedure Writers	P - Procedure Dev	050-00334/2009-005
191 - Team interactions LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2010-003
Number of Items for this Docket: 8			
Percent of Total for this Docket: 30			
Problem Identification & Resolution / LER			
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00334/2011-002-01
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01
142 - Operating experience (OE) review LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01
150 - Programmatic deficiency	O - Operations	O - Control Room Ops	050-00334/2011-002-01

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 27

National Average: 30

2x National Average: 60

National Median: 18

Average for Selected Dockets: 27

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / LER			
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01
Number of Items for this Docket: 5			
Percent of Total for this Docket: 19			
Training / LER			
102 - Individual knowledge LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01
102 - Individual knowledge LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00334/2011-002-01
187 - Action implementation LTA	G - Engineering	G - Design	050-00334/2011-002-01
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00334/2011-002-01
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2011-002-01
Number of Items for this Docket: 6			
Percent of Total for this Docket: 22			
Total Items for this Docket: 27			
