

NRC INSPECTION MANUAL

IRIB

CHANGE NOTICE 25-001

DELETED:

	<u>Number</u>	<u>Date</u>
1.	IP 50001	09/12/17
2.	IP 50003	09/12/17
3.	IP 71007	10/03/17
4.	IP 88001	04/15/1994
5.	IP 89001	09/02/1997

TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IP 50001	02/04/25
	IP 50003	02/04/25
	IP 71007	02/04/25

TRAINING: No special training is required for any documents issued with this Change Notice.

REMARKS: IP 50001, "Steam Generator Replacement Inspection." Researched commitments for 4 years and found none. Minor editorial changes. This completes the 5-year review.

IP 50003, "Pressurizer Replacement Inspection." Researched commitments for 4 years and found none. Minor editorial changes. This completes the 5-year review.

IP 71007, "Reactor Vessel Head Replacement Inspection." Researched commitments for 4 years and found none. Minor editorial changes. This completes the 5-year review.

IP 88001, "On-site Construction." Deleted from the Inspection Manual due to the revised IMC 2602 was issued in mid-December (CN 22-026), and NMSS/DUWP discontinued use of IP 88001. (ML24005A325)

IP 89001, "In-Situ Leach (ISL) Facilities." Deleted from the Inspection Manual due to IP no longer needed; requirements were incorporated in the inspection procedures under IMC 2801 and IMC 2602.

EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

DISTRIBUTION:

- ☒ Standard
☐ Official Use Only (OUO)-Security Related Information.

Please contact: _____ Phone: _____

END