



W. R. McCollum, Jr.
Vice President

Duke Energy

Oconee Nuclear Station
7800 Rochester Highway
Seneca, SC 29672
(864) 885-3107 OFFICE
(864) 885-3564 FAX

August 6, 2001


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Duke Energy Company
Oconee Nuclear Station, Unit 2
Docket No. 50-270
Unit 2 EOC 18 Refueling Outage
Inservice Inspection Report
Third Ten-Year Inservice Inspection Interval

Please find attached a copy of the Inservice Inspection Report for Oconee Unit 2 End of Cycle 18 Refueling Outage. This report is submitted pursuant to Section XI of the ASME Boiler and Pressure Vessel Code, 1989 Edition, with no addenda, Article IWA 6230.

If there are any questions you may contact R. P. Todd at (864) 885-3418.

Very truly yours,



W. R. McCollum, Jr.
Site Vice-President

Attachment

A047

U. S. Nuclear Regulatory Commission
August 6, 2001
Page 2

xc wo/attachment: Mr. Luis A. Reyes
Administrator, Region II
U.S. Nuclear Regulatory Commission
61 Forsyth Street, S. W., Suite 23T85
Atlanta, GA 30303

D. E. LaBarge, Projects Manager
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. M. C. Shannon
Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Virgil R. Autry
Division of Radioactive Waste Management
Bureau of Land and Waste Management
SC Dept. of Health & Environmental Control
2600 Bull St.
Columbia, SC 29201