

FORM TI-1 CASE RESOLUTION

Case Status

Open

Closed

RCODE:40070

Region: IV

OLD - Complete Name, Address, Contact, Phone Number:

Anaconda Minerals Company
2550 Denali Street, Suite 1000
Anchorage, Alaska 99503

NEW - Complete Name, Address, Contact, Phone Number:

Atlantic Richfield Company (ARCO)
444 South Flower Street
Los Angeles, CA 90071
Mike Hagood, Environmental Site Manager
(213) 486 - 3685

Agreement State Licensee? (Double Check)

Yes

No

Moved to an Agreement State?

Yes

No

Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other)

NRC Database

CD-ROM

Internet

Telephoned Alaska Miners Association, Atlantic Richfield Co. (ARCO) HQ Butte, MT
Telephoned ASOMA, a subsidiary of SPECTRO Analytical Instruments Corporation

Describe Communication with Registration Vendor:

Contacted ASOMA, a subsidiary of SPECTRO Analytical Instruments Corporation

Vendor Follow-up Action:

Contacted ASOMA, Robert Bartek (830-798-8786) provided final disposition
ASOMA/SPECTRO Analytical Instruments Corporation
1515 North Hwy 281
Marble Falls, Texas 78654

Final Action Taken:

Update database

Cause of Bad Address/Lesson Learned:

The facility at Denali Street is closed. Alaska Miners Association said that facility had been out of operations for several years and that it had been bought by ARCO.

ARCO absorbed the Anaconda Mineral Company in 1977.

Mike Hagood, the point-of-contact at ARCO, said that this was a short-lived project and that the Denali Street location was probably its headquarters.

According to Robert Bartek, at ASOMA/SPECTRO, the sources were installed in the Anaconda facility in Anchorage, Alaska circa 5/19/82. The gauges were returned to ASOMA on 4/6/89. The sources removed by ASOMA on 12/6/89.

FORM TI-2 DEVICE INFORMATION

RCODE: 40070								
ID	Model Number ¹	Serial Number	Isotope	Activity mCi	Sold Date	Vendor	Status (A ² or N ³)	Comments
1	8010	016	Am-241	5.0	19822	6-2788G	A	Both sources returned to vendor (SPECTRO / ASOMA); vendor removed sources from devices
2	8010	016	Cd-109	5.0	19822	6-2788G	A	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

FORM TI-3 GENERAL LICENSEE INSPECTION DOCUMENTATION

¹Include only registerable gauges identified by Headquarters as "open" cases.

²Accounted for: A device is accounted for if (1) the device is located at the licensee's facility, (2) it has been verified that the device has been transferred to an authorized recipient or properly disposed, or (3) a reasonable assurance has been provided that the device has been transferred to an authorize recipient or properly disposed.

³Not Accounted for: A device is not accounted for if the location of the device is unknown and/or the licensee cannot provide a reasonable assurance that the device has been transferred to an authorized recipient for proper disposal.

RCODE: 40070	
General Licensee Information:	
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
	Atlantic Richfield Company (ARCO) 444 South Flower Street Los Angeles, CA 90071 Mike Hagood, Environmental Site Manager (213) 486 - 3685
Results of inspection: (check the appropriate boxes)	
	The general licensee of record is located at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for;
	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
X	Other: (explain) GL not inspected. Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record. All GLD are accounted for; sources returned to vendor ASOMA/SPECTRO.
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:

Inspector: Jefferey Cruz / Lawrence Donovan, Health Physicists, Nuclear Materials Inspection Branch RIV

Approved by: Mark R. Shaffer, Chief, Nuclear Materials Inspection Branch RIV





November 21, 2000

Jeff Cruz
US Nuclear Regulatory Commission

Fax # 817-860-8188

RE: S/N 016
Anaconda
Anchorage, AK

Dear Mr. Cruz,

Please find attached the journal log of the referenced analyzer. Per the log, the Cd-109 and Am-241 sources were removed from the system on December 6, 1989.

If you have any questions, please do not hesitate to contact me at x250.

Sincerely,

A handwritten signature in cursive script, appearing to read "Robert P. Bartek".

Robert P. Bartek

Encl. Journal Log

Shipped to

5/19/82

Anaconda - Anchorage, AK

12/20/82

ASOMA - Austin, TX

modification

1/31/83

Anaconda - Anchorage, AK

4-6-89

ASOMA - Austin, TX

Returned

12-6-89

Sources Removed