

Form TI-1 Case Resolution

Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: __3592__		
Region: __1__		
OLD - Complete Name, Address, Contact, Phone Number: Northbrook Metals Pennsauken, NJ 08110		
NEW - Complete Name, Address, Contact, Phone Number:		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) New Jersey Department of the Treasury, Division of Revenue reports the "Home Jurisdiction of Northbrook Metals is Illinois. Its corporate status in New Jersey was revoked in 1985 for failure to pay taxes. It last filed a required annual report in September 1983.		
Describe Communication with Registration Vendor: Fred Hanser, Panametrics (781-899-2719, ext. 217). The vendor reported that the device received by this company was on a list of devices for which it could not confirm proper disposal (i.e., the company has not returned the device nor has it made the vendor aware of disposal by another means).		
Vendor Follow-up Action:		
Final Action Taken:		
Cause of Bad Address/Lesson Learned:		

Form TI-2: Device Information

RCODE: ___3592_____								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	Panalyzer 4000		²⁴¹ Am	10	19814	20-07181-04G	N	
2	Panalyzer 4000		²⁴¹ Am	10	19814	20-07181-04G	N	
3	Panalyzer 4000		²⁴¹ Am	10	19811	20-07181-04G	N	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

A - Source accounted for

N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCODE: ___ 3592 _____	
General Licensee Information:	
<input type="checkbox"/>	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
<input type="checkbox"/>	
Results of inspection: (check the appropriate boxes)	
<input type="checkbox"/>	The general licensee of record is located at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for;
<input checked="" type="checkbox"/>	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
<input type="checkbox"/>	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:
<input type="checkbox"/>	
<input type="checkbox"/>	

We have not been able to locate information for this licensee that would let us identify the responsible corporation with any certainty. It appears likely the company is out of business. The only address we have for this general licensee is "Pennsauken, NJ." Without more information, there is little hope of tracking the gauges and further effort is not justified.

Inspector: Keith Brown, Health Physicist
Nuclear Materials Safety Branch 2

Approved By: John D. Kinneman, Chief
Nuclear Materials Safety Branch 2