

FORM TI-1 CASE RESOLUTION

Case Status as of 04/17/2002

Open

☒ Closed

RCODE: 32807

Region: IV

OLD - Complete Name, Address, Contact, Phone Number:

AMAX Coal Company
1901 Energy Court
Gillette, WY 82716

NEW - Complete Name, Address, Contact, Phone Number:

RAG Coal West, Inc.
Eagle Butte Mine
P.O. Box 3040
Terry Bosecker, RSO, 307-687-3456

Agreement State Licensee? (Double Check)

☐ Yes

☒ No

Moved to an Agreement State?

☐ Yes

☒ No

Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other)
Used RAG Coal West specific license (RIV) for contact information.

Describe Communication with Registration Vendor:

NONE in RIV. Licensee contacted Bob Burkhart @ ThermoMeasuretech.

Vendor Follow-up Action:

NONE in RIV. ThermoMeasuretech FAXed the licensee information pertaining to the purchase and subsequent return of the GL device.

Final Action Taken:

Update RIV database, notify NRC GL Manager

Cause of Bad Address/Lesson Learned:

Old address/name was not accurate.

AMAX Coal West, Inc. (Wyoming Mining Operations Laboratory) became RAG Coal West, Inc. in 2000.

FORM TI-2 DEVICE INFORMATION

RCODE: 32807								
ID	Model Number ¹	Serial Number	Isotope	Activity	Sold Date	Vendor	Status (A ² or N ³)	Comments
1	Source head: 9254	Source serial: LP-0401 Source head serial: B373	238-Pu	30 mCi	09/01/88	Texas Nuclear	A	Bob Burkhart @ ThermoMeasure Tech researched both computer and paper records. Records indicated that only 420 of these units were sold. After reviewing the records, he came to the conclusion the only ONE device was sold to AMAX (contrary to NRC records indicating two devices). The device was returned to Texas Nuclear 10/19/1989.
For additional GLD's received by the licensee identified during the inspection: NONE								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

¹Include only registerable gauges identified by Headquarters as "open" cases.

²Accounted for: A device is accounted for if (1) the device is located at the licensee's facility, (2) it has been verified that the device has been transferred to an authorized recipient or properly disposed, or (3) a reasonable assurance has been provided that the device has been transferred to an authorized recipient or properly disposed.

³Not Accounted for: A device is not accounted for if the location of the device is unknown and/or the licensee cannot provide a reasonable assurance that the device has been transferred to an authorized recipient for proper disposal.

FORM TI-3 GENERAL LICENSEE INSPECTION DOCUMENTATION

RCODE: 32807

General Licensee Information:

Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:

RAG Coal West, Inc.
Eagle Butte Mine
P.O. Box 3040

Terry Bosecker, RSO, 307-687-3456

Results of inspection: (check the appropriate boxes)

The general licensee of record is located at the address of record and

☐ all GLD are accounted for

☒ not all GLD are accounted for

The general licensee of record is not located at the address of record, however GLD are being used under new ownership at the address of record and

☐ all GLD are accounted for

☒ not all GLD are accounted for

The general licensee of record is not located at the address of record, however they are using GLD at another location and

☐ all GLD are accounted for

☒ not all GLD are accounted for;

Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.

X

Other: (explain) RAG Coal West, Inc. not inspected. (Note: They have a specific license 49-26963-03.) GL devices accounted for (returned to vendor 10/19/1989).


Gauge Information:

ID

For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge: All accounted for.

Inspector : Janine F. Katanic, Health Physicist, Nuclear Materials Inspection Branch, RIV

Approved by: Mark R. Shaffer, Chief, Nuclear Materials Inspection Branch, RIV


4/18/02



Oct 4, 1988

Page 1

1859 AMAX COAL COMPANY
Gillette, WY

MODEL	SERIAL #	ISOTOPE	ACTIVITY	SOURCE #	SHIP DATE
9254	B373	Pu-238	30 mCi	LP-0401	09/01/88


NATURE SAVER™ FAX MEMO 01616		Date 4/16/02	not pages 2
To Terry Bosecker	From Bob Burkhardt		
Co / Dept AMAX	Co Therma MesurTech		
Phone #	Phone #		
Fax #	Fax #		

APR. 16. 2002 1:20PM

OKEMAH GILLETTE

THERMO MEASURETECH

5129889339

NO. 918 P. 1
T-912 P.02/02 F-204ATTN: JANINE KATANIC

ACKNOWLEDGEMENT OF RECEIPT OF RADIOACTIVE MATERIAL

DATE: October 19, 1989COMPANY NAME: AMAX COAL COMPANYADDRESS: 1901 Energy CourtGillette, WY 82716Attn: Bruce A. Taylor

This is to verify that Texas Nuclear has received the radioactive material described below pursuant to applicable regulations as authorized by our Texas License LO-3524:

Isotope	Activity	Source Serial No.	Gauge Manufacturer	Source Head Model No.	Source Head Serial No.
<u>Pu-238</u>	<u>30 mCi</u>	<u>LP-0401</u>	<u>Texas Nuclear</u>	<u>9254</u>	<u>B373</u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

If you have questions or if we may be of further assistance, please do not hesitate to let us know.

SIGNED: Jennifer AtkinsTITLE: Technical Services Coordinator