

Form TI-1 Case Resolution

Case Status	Open	Closed X
RCODE: 52951		
Region: 1		
OLD - Complete Name, Address, Contact, Phone Number: Nowsco Well Services, Inc. McKinley Street Brookville, Pennsylvania		
NEW - Complete Name, Address, Contact, Phone Number: BJ Services Company Corporate HQ 8701 New Trails Drive The Woodlands, TX 77381 (281) 363-7500		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) Charlotte Bellon, Corporate Radiation Safety Officer, BJ Services (713-351-2578) stated, according to her database, the two gauges were transferred to other facilities: S.N. B5537 is in the Dunbar, WV facility and S.N. B5835 is in the Clarksburg, WV office. Nowsco was purchased by BJ Services in 1996, Attached is a faxed letter referring to their 10.A license, No. 42-19649-01, listing all operating facilities at which licensed material will be stored.		
Describe Communication with Registration Vendor: Jon George, Service Engineer, TN Technologies (512-388-9308). The vendor shows these sources were shipped to a facility on McKinley street in 1989 and 1990. The former was gauge serial no. B5537 and source serial No. GG4476. The latter was gauge serial no. B5835 and source serial No. GG5266. Neither has been returned.		
Vendor Follow-up Action: None		
Final Action Taken: Update HQ database		
Cause of Bad Address/Lesson Learned: Company went out of business and devices were transferred out of the Region.		

RCODE: 52951

Name: Nowsco Well Services, Inc

C:\ORPCheckout\FileNET\ML021650295.wpd

Form TI-2: Device Information

RCODE: 52951								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	5190		¹³⁷ Cs	200	19902	L01105	A	
2	5192		¹³⁷ Cs	100	19902	L01105	A	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

A - Source accounted for

N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCODE: 52951	
General Licensee Information:	
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
X	BJ Services Company Corporate HQ 8701 New Trails Drive The Woodlands, TX 77381 (281) 363-7500
Results of inspection: (check the appropriate boxes)	
	The general licensee of record is located at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
X	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
X	all GLD are accounted for
	<u>not</u> all GLD are accounted for;
	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:

Inspector: Stephanie Tullio, Nuclear Safety Intern
Nuclear Materials Safety Branch 2

Completion Date: 4/09/02

Approved By: John D. Kinneman, Chief
Nuclear Materials Safety Branch 2