

Enclosure: Landauer TLD Results

Period: July 2 through October 2, 2002

<u>Location</u>	<u>Gross Exposure, Standard Calendar Quarter (millirem)</u>
1. Reed Bed #1, Cell A	1693.3
2. Reed Bed #2, Cell B	1047.7
3. Fence by Reed Bed #1 (east)	59.7
4. Settling tanks rail - by Reed Bed #1	274.9
5. Settling tanks rail - by Secondary Digester/Trickling Filters	66.0
6. Rear Fence (north)	32.3
7. Fence by Reed Bed #2 (west)	25.1
8. Light Switch of Storage Building	25.4
9. Secondary Digester - center of west side	28.7
10. 2 nd Story rail by Office back door	29.1
11. Front fence (south)	25.0
12. Support rail of stairway to Office back door	29.0
13. Primary Digester - top of ladder	Missing
14. Secondary Digester - center of east side	168.3
15. Settling tanks rail - path to Laboratory Building	32.0
16. Office	24.1
xx. Deploy dosimeter	19.3
xx. Transit dosimeter	18.1