



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

December 16, 2002

Docket No. 03020934
Control No. 132356

License No. 37-23341-01

Dale Jakoby
Superintendent
Wastewater Treatment Facility
Borough of Royersford
300 Main Street
P. O. Box 188
Royersford, PA 19468

SUBJECT: REPORT OF THIRD QUARTER 2002 EFFLUENT RELEASES, CONTROL NO. 132356, AND THIRD QUARTER 2002 ENVIRONMENTAL TLD MONITORING RESULTS

Dear Mr. Jakoby:

Enclosed is the quarterly report of effluent releases made by UniTech Group Services, Inc. during the third quarter of 2002 to the Borough of Royersford Wastewater Treatment Facility. Also enclosed are the results of the environmental TLD monitoring performed by the NRC at the Royersford Wastewater Treatment Facility for the periods of July 2 through October 2, 2002, (third quarter 2002). If you have any questions about the information provided with this letter, please contact me at (610) 337-5040.

Thank you for your cooperation.

Sincerely,

Original signed by Elizabeth Ullrich

Betsy Ullrich
Senior Health Physicist
Nuclear Materials Safety Branch 2
Division of Nuclear Materials Safety

Enclosures:

1. UniTech Services Group, Third Quarter 2002 Effluent Report
2. Third Quarter 2002 TLD Monitoring Results

cc w/ enclosures:

Daniel R. Neely, RSO, UniTech
Michael Fuller, UniTech
David Allard, PADEP
Ivna Shanbak, PADEP

DOCUMENT NAME: C:\ORPCheckout\FileNET\ML023500128.wpd

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	DNMS/RI		
NAME	EUIlrich/EXU					
DATE	12/16/2002					

OFFICIAL RECORD COPY

Enclosure: Landauer TLD Results

Period: July 2 through October 2, 2002

<u>Location</u>	<u>Gross Exposure, Standard Calendar Quarter (millirem)</u>
1. Reed Bed #1, Cell A	1693.3
2. Reed Bed #2, Cell B	1047.7
3. Fence by Reed Bed #1 (east)	59.7
4. Settling tanks rail - by Reed Bed #1	274.9
5. Settling tanks rail - by Secondary Digester/Trickling Filters	66.0
6. Rear Fence (north)	32.3
7. Fence by Reed Bed #2 (west)	25.1
8. Light Switch of Storage Building	25.4
9. Secondary Digester - center of west side	28.7
10. 2 nd Story rail by Office back door	29.1
11. Front fence (south)	25.0
12. Support rail of stairway to Office back door	29.0
13. Primary Digester - top of ladder	Missing
14. Secondary Digester - center of east side	168.3
15. Settling tanks rail - path to Laboratory Building	32.0
16. Office	24.1
xx. Deploy dosimeter	19.3
xx. Transit dosimeter	18.1