



Section through a weld-overlay repair of a through-wall crack in a 6-inch diameter TP304 stainless steel pipe after loading.
(Degraded Piping Program, DRB No. 1.2.3.6)

AST