

S O U T H W E S T R E S E A R C H I N S T I T U T E

Department of Quality Assurance
Calibration Laboratory

WORK ORDER 06/09/93

Dev.ID Nomenclature
2417 PRESSURE GAUGE

Manufacturer	Model	Serial Number	Int	SwRI ID
WIKA	30 PSI	1593003	12	NONE

User	Pgm Accuracy	Procedure	Acq.Date
DIV20 B57 NARASI SRIDHAR	2 MFGR	MFGR	06/08/93

Remarks

Discrepancy/Condition Received:

- F Received out of tolerance, repaired to specifications
- G Received in tolerance, minor adjustments/repairs made
- J Received in tolerance, no adjustments made
- K Received out of tolerance, adjusted to specifications
- S Received into the system, introduced or reactivated

Used in Program:

- | | | | |
|----------------------------|----------|----------------------------|------------------|
| 1 <input type="checkbox"/> | DOD/NASA | 5 <input type="checkbox"/> | 1 and 2 |
| 2 <input type="checkbox"/> | NUCLEAR | 6 <input type="checkbox"/> | 1, 2, 3, 4 and 8 |
| 3 <input type="checkbox"/> | GLP | 7 <input type="checkbox"/> | CNR |
| 4 <input type="checkbox"/> | SPPE | 8 <input type="checkbox"/> | SwRI |

Deg.F: __ Rel.Hum: __ Emp #: __ Record #: __

Calibration Date: _____ Due Date (next Cal) _____ Cal Location _____

Summary/Action Taken: THE ABOVE PRESSURE GAUGE WAS RECEIVED OUT OF TOLERANCE
WHEN SUBMITTED FOR CALIBRATION. THE PRESSURE GAUGE DID NOT MEET MANUFACTURER'S
SPECIFICATIONS AND THUS WAS NOT CALIBRATED. THE FOLLOWING READINGS WERE OBTAINED:

STANDARD READING: 30 psi, 20 psi, 10 psi, 5 psi

UNIT UNDER TEST: Past full scale, 24 psi, 14 psi, 8 psi, respectively

Calibration Standards Used(Device IDs): _____

Return Item to: _____ Phone: (____) _____

Accessories: _____

Completed: __ / __ / __ By: _____ Hrs: _____ Chgr #: _____