

S O U T H W E S T R E S E A R C H I N S T I T U T E

Department of Quality Assurance
Calibration Laboratory

WORK ORDER 06/09/93

Dev.ID Nomenclature
2418 PRESSURE GAUGE

Manufacturer	Model	Serial Number	Int	SwRI ID
WIKA	200 PSI	1593004	6	NONE

User	Pgm Accuracy	Procedure	Acq.Date
DIV20 B57 NARASI SRIDHAR	2 MFGR	MFGR	06/09/93

Remarks

Discrepancy/Condition Received: _____

- F ___ Received out of tolerance, repaired to specifications
- G ___ Received in tolerance, minor adjustments/repairs made
- J ___ Received in tolerance, no adjustments made
- K ___ Received out of tolerance, adjusted to specifications
- S ___ Received into the system, introduced or reactivated

Used in Program:

- | | | | |
|-------|----------|-------|------------------|
| 1 ___ | DOD/NASA | 5 ___ | 1 and 2 |
| 2 ___ | NUCLEAR | 6 ___ | 1, 2, 3, 4 and 8 |
| 3 ___ | GLP | 7 ___ | CNR |
| 4 ___ | SPPE | 8 ___ | SwRI |

Deg.F: __ Rel.Hum: __ Emp #: _____ Record #: _____

Calibration Date: _____ Due Date (next Cal) _____ Cal Location _____

Summary/Action Taken: THE ABOVE PRESSURE GAUGE WAS RECEIVED OUT OF TOLERANCE
WHEN SUBMITTED FOR CALIBRATION. THE PRESSURE GAUGE DID NOT MEET MANUFACTURER'S
SPECIFICATIONS AND THUS WAS NOT CALIBRATED. THE FOLLOWING READINGS WERE OBTAINED:

STANDARD READING: 50 psi, 100 psi, 150 psi, 200 psi

UNIT UNDER TEST: 60 psi, 115 psi, 160 psi, past full scale, respectively

Calibration Standards Used(Device IDs): _____

Return Item to: _____ Phone: (____) _____ - _____

Accessories: _____

Completed: __ / __ / __ By: _____ Hrs: _____ Chgr #: _____ - _____