



CENTER FOR NUCLEAR WASTE REGULATORY ANALYSES

QUALITY ASSURANCE

SURVEILLANCE REPORT

PROJECT NO.: 20.5704-042

REPORT NO.: 93-01

PAGE 1 OF 1

SURVEILLANCE SCOPE:

Slow Strain Rate Tests of IWPE TASK 2

REFERENCE DOCUMENTS:

IWPE PROJECT PLAN, QAP-001

STARTING DATE: 1/11/93

ENDING DATE: 1/15/93

QA REPRESENTATIVE: R.D. BRIENT

PERSONS CONDUCTING TEST / EXAM / ACTIVITY:

D. DUNN

SATISFACTORY FINDINGS:

1. Confirmed calibration of Load cells and LVDTs, Electrometer, and Thermometer used to monitor test parameters and results.
2. Reviewed set-up of the data acquisition system and the measurement parameters. Calibration values for Load cells and LVDTs are loaded into the computer to provide direct indication of loads and extension.
3. Reviewed Scientific Notebook #027 entries for test SSET 3317 on pg. 55, as well as other in-process and initial entries.

UNSATISFACTORY FINDINGS:

None

NONCONFORMANCE REPORT NO.:

N/A

ATTACHMENTS:

None

RECOMMENDATIONS / ACTIONS

Some minor recommendations were made to enhance Scientific Notebook information. No action is required.

APPROVED:

CENTER DIRECTOR OF QUALITY ASSURANCE

DATE:

1/15/93

DISTRIBUTION:

ORIGINAL - CENTER QA DIRECTOR
ORIGINATOR
PRINCIPAL ENGINEER G. CRADNOLINO
ELEMENT MANAGER P. NAIR
D. DUNN

B. SAGAR