



APPENDIX B MICROFICHE INDEX

<u>Appendix</u>	<u>Title</u>
B.1	Report of Preliminary Site Exploration - September 1966, Dames and Moore, Chicago, Illinois
B.2	Foundation Investigation - December 1967, Dames and Moore, Chicago, Illinois
B.3	Earthquake and Wind Analysis - Plant Effluent Stack, November 1968, H. J. Saxon & Associates, Engineers, San Francisco, California
B.4	Earthquake and Wind Analysis - Underground Structures, March 1969, H. J. Sexton & Associates, Engineers, San Francisco, California
B.5	Criticality Safety Basis for Project I Fuel Storage, May 1975, Battelle Pacific Northwest Laboratories, Richland, Washington
B.6	Fuel Storage System Design Report - Project I Fuel Storage, April-May 1975, Programmed & Remote Systems Corporation, St. Paul, Minnesota
B.7	Seismic Shock Environment Test of Simulated Nuclear Fuel Storage Basket, August 1975, Department of the Army, Construction Engineering Research Laboratory, Champaign, Illinois
B.8	DELETED
B.9	Report of Fault Investigation at the Midwest Fuel Reprocessing Plant near Morris, Illinois, October 1974; Dames & Moore, Chicago, Illinois
B.10	Report of Geologic and Ground Water Investigation, Proposed Spent Fuel Storage Facility near Morris, Illinois, September 1975; Dames & Moore, Chicago, Illinois
B.11	Evaluation of Foundation Recommendations - Project IV -Fuel Storage Capacity Expansion near Morris, Illinois (letter report) May 1977; Dames & Moore, Chicago, Illinois
B.12	Report of Ground Water Investigations - Project IV - Fuel Storage Capacity Expansion near Morris, Illinois, August 1977; Dames & Moore, Chicago, Illinois
B.13	Report of Geophysical Investigations - Project IV - Fuel Storage Capacity Expansion near Morris, Illinois, July 1977; Dames & Moore, Chicago, Illinois



Appendix

Title

- B.14 Report of Geologic Investigations - Project IV - Storage Capacity Expansion near Morris, Illinois, August 1977; Dames & Moore, Chicago, Illinois
- B.15 Criticality Safety Analysis for Square Tube Storage Baskets at the Morris Operation, May 1987; G.E.
- B.16 Morris Square Tube Basket Stress Report Revision, June 1987; G.E.
- B.17 Proposed Approach to Evaluate Adequacy of Ground Water Monitoring System, February 1993; Dames & Moore, Chicago, Illinois
- B.18 Ground Water Modeling & Specs for Monitoring Wells, August 1993; Dames & Moore, Chicago, Illinois
- B.19 Quality Assurance Plan Monitoring Well Installation, October 1993; Dames & Moore, Chicago, Illinois
- B.20 Final Report Transport Modeling for Accidentally Released Water from Spent Fuel Storage Basin, October 1993; Dames & Moore, Chicago, Illinois
- B.21 Ground Water Monitoring Well Network Summary & Installation Report, January 1994; Dames & Moore, Chicago, Illinois
- B.22 Offsite Dose Calculation Manual, July 1994; GE
- B.23 Radwaste System Description, July 1994; GE