

(10-2003)
10 CFR 2.201

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Radiometrics REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-36643	4. LICENSE NUMBER(S) 34-30944-01	5. DATE(S) OF INSPECTION 1/25/05	
6. INSPECTION PROCEDURES USED 87125	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3225	2. PRIORITY 5	3. LICENSEE CONTACT James T. Ryan	4. TELEPHONE NUMBER 440/277-5538
-----------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: 1/2010

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

Licensee is a gauge repair, testing, replacement firm located in Lorain, Ohio with a client base through out Ohio and the eastern states. The licensee takes wipe surveys of client gauges and performs analysis of the samples to ensure compliance with regulations. Additionally, licensee performs the installation and shutter testing of Berthold gauges in the eastern half of the United States as the authorized representative for Berthold. The operations consist of two in office personnel and four field personnel. Licensee performs operations at client facilities primarily with analysis of wipes performed at the laboratory in Lorain, Ohio.

Performance Observations

The inspector toured the laboratory and work spaces. The inspector interviewed the RSO and support staff. Licensee appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

