

ATL TEAM

PERSONAL COMMUNICATION NOTES

DATE: 1 / 26 / 2005 TIME: 10:30 am PROJECT TITLE: LES EIS for NM


BETWEEN: Steve Carr, General Manager OF: Wallach Concrete, Inc.

LOCATION: Eunice, NM TELEPHONE No.: (505) 392-5204

AND: Milton Gorden of ATL Team (the caller) TELEPHONE No.: (301) 515-6781

DISCUSSION:

Mr. Carr was contacted to discuss the nature of the seep that is described in the DEIS that appears at the bottom of one of the pits on the northwest side of Wallach Concrete. Mr. Carr believed the pit was surrounded by walls of about 30 feet on all sides. He thought there was about 15 feet of water in the pit at this time because the area has received approximately 40 inches of rain over the past year. He stated that normally there was only about 12 inches of water in the bottom. He recommended contacting David Raines (505-394-2155), an operations person who works at the quarry to obtain more accurate information.

CALLER SIGNATURE: 

PROJECT MANAGER SIGNATURE: 