



**ALONSO & CARUS** iron works inc.  
ROAD 868, KM. 0.09 BO. PALMAS, P.O. BOX 566, CATAÑO, PUERTO RICO 00963

JP: NOV  
11/95

December 5, 1995

Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW  
Suite 2900  
Atlanta, GA 30323-0199

REF: NRC Docket No.  
030-20541  
License #52-21350-01

Gentlemen:

Reference is made to the inspection performed by NRC Radiation Specialist, Mr. Jose M. Diaz on October 16th., 1995 at our facilities. Mr. Diaz examined our records, procedures, all filed documents, interviewed our personnel and surveyed our storage facilities, in which he sited us in various NRC requirements as follows:

- 1- Pocket dosimeter be checked by calibration at intervals not to exceed one (1) year as specified in 10 CFR 34.44(C).
- 2- Alarm rate meter be checked by calibration at intervals not to exceed one (1) year as specified in 10 CFR 34.33(F)(4).

In reference to your notice of violation from inspection report No.(52-213350-01-95-01) please note the following reasons and corrective action on your Docket No. 030-20541:

- 1- REASON: Employee had his personal instrument with calibration dated exceeding one (1) year interval.
- 2- CORRECTIVE STEPS: Instruments have been replaced immediately after sited in presence of NRC Inspector, and RSO has revised 10CFR 34-(F)(4) over again with employee for a complete understanding.

...../

# ALONSO & CARUS iron works inc.

Nuclear Regulatory Commission  
Atlanta, GA 30323-0199

- 2 -

- 3- AVOID FURTHER VIOLATIONS: Daily inspection check list modification to include in check list the daily revision of equipment and calibration expiration date of all personnel and related instrumentation. (Enclosed is original and new documents for your revision).
- 4- We have achieved complete compliance with your written approval or response to our corrections.

Cordially yours,

ALONSO & CARUS IRON WORKS, INC.

  
Wilfredo Rivera, RSO

Enclosure