



Explanation

- ★ Extraction Well
- Well Point Installed in 2001
- Monitor Well Installed in 1998 and 1999
- Monitor Well or Well Point Installed Before 1998
- Monitor Well Installed after 1999
- December 1999 Geoprobe Hole
- October 2002 Geoprobe Hole
- ▲ October 1999 Well Point (Black Label)
- ▲ October 1999 Backhoe Pit or Test Pit
- December 1999 Test Pit
- ▲ Sediment and Surface Water Sample Location
- ▲ Surface Water Sample Location (Red Label)
- - - Approximate Boundary Between Terrace East and Terrace West Ground Water Systems
- - - Approximate Position of Buried Escarpment
- Former Raffinate Pond
- Former Ore Pile
- Approximate Area Affected by Irrigation
- 10 Foot Contour
- N5072 Navajo Nation Road and Number



U.S. DEPARTMENT OF ENERGY GRAND JUNCTION, COLORADO	Prepared by S.M. Stoller Corporation Under DOE Contract No. DE-AC01-02GJ79491
Plate 1: Shiprock Site Features, Wells/Sampling Locations, and Remediation Components	
DATE PREPARED:	FILE NAME:
February 18, 2004	U0194400-01

D-01