



Westinghouse  
Electric Corporation

11 Stanwix Street  
Pittsburgh, PA 15222  
(412) 642-3880

.July 31, 1996

Ronald R. Bellamy, Ph.D., Chief  
Decommissions and Laboratory Branch  
Nuclear Materials Safety  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

Subject: Bloomfield Lamp Plant Final Survey Report for Buildings 7, 8, 9 and 10A and the Surrounding Property on the East Side of Arlington Avenue; License No. SMB-1527 (Mail Control No. 115462)

Dear Dr. Bellamy:

Westinghouse Electric Corporation has completed the remediation of Buildings 7, 8, 9, and 10A and the surrounding property on the east side of Arlington Avenue at the former lamp plant in Bloomfield, NJ. Enclosed are two copies of the Westinghouse Bloomfield Lamp Facility Final Survey Report on Buildings 7, 8, 9, and 10A, Volumes I-X, July 1996, Revision O. This report contains the results of the final survey performed by Scientific Ecology Group, Inc. to verify unrestricted release status for these locations at the facility.

This report is also provided as a supplement to the *Radiological Decontamination Confirmatory Survey, Westinghouse Bloomfield Lamp Plant Buildings 7, 8, and 9 (includes Building 10A) issued in 1992. The report regarding Bloomfield Lamp Plant Trench Closure Package, Building 7 Courtyard, Building 7 First Floor, Building 7/8 Trench, Building 8/9 Trench, Building 9/10A and the Dose Assessment* which was issued April 9, 1996.


July 31, 1996

Page 2

Please contact us if you have any questions:

C. W. Bickerstaff, Manager  
Industrial Hygiene and Radiation Safety Officer  
License # SMB 1527  
(412) 642-3880

Sincerely,

  
C. W. Bickerstaff, Manager  
Industrial Hygiene  
Environmental Affairs

Attachments