		622 Pho	O Culebra Road, P.O. Institute Quality S Institute Calibration ne: 210-522-5215 Fa	ystems Laboratory (210-522-4834	ГЕ®	Accredited Certificate #
	®		Certificate of Ca	libration		0972-01
	Submitted By:	DIV20		Work Order:	303068183	
	Address:	B57		Date Issued:	Mar 3, 2006	
		DON BANNON		Calibration Date:	,	
Man	ufacturer Model:			*Calibration Due:	-	
		TEMPERATURE/HUMI	DITY INDICATOR	Calibration Location:	-	
		Y2540054			Temp. 73.0°F	
	Asset No:			**Data Type:	FOUND-LEFT	
	Procedure:	TEMPERATURE/HUMIE	DITY, MAY/03			
is date termin eported certair	 **Found/Left = adjunction ation of in-/out-of-tole d uncertainty calculate nty with a coverage face 	stment and/or repair was not re erance or compliance/noncomp	equired, As Left = adjusted liance. See Remarks or att Guide to the Expression of % confidence level.	e as any number of factors may ca and/or repaired was required. Th ached Measurement Report with t Uncertainty in Measurement" (Gl , SN Y1120007, AN 010786	e client has sole re he same Work Or	esponsibility for der number for data.
anda	rds Used					
	Serial No.	Manufacturer	Model	Description		Cal Due
6404	9806123	THUNDER SCIENTIFIC	2500	HUMIDITY GENERA	TOR	Jun 13, 06
9414	A25788	HART SCIENTIFIC	1502A	TEMPERATURE REA	ADOUT	Aug 02, 06
)692	632656	HART SCIENTIFIC	5618	PLATINUM RTD		Aug 02, 06

Reviewed Ky: - blf() jrg() pwc()-wgh() Metrology Technician m:\a2la1.rpt Rev date August 15, 2005

elling 0 Measurements by: Bob Trollinger Metrology Technician

Page 1 of 1