



*Docket File Information*  
**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**



1. LICENSEE <b>Driesenga &amp; Associates</b> REPORT 2006-001	2. NRC/REGIONAL OFFICE <b>Region III</b>
---	---

3. DOCKET NUMBER(S) 030-33782	4. LICENSE NUMBER(S) 21-26634-01	5. DATE(S) OF INSPECTION May 16, 2006
----------------------------------	-------------------------------------	--

6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM 03121	2. PRIORITY 5	3. LICENSEE CONTACT James Henning	4. TELEPHONE NUMBER 616.396.0255
---------------------	------------------	--------------------------------------	-------------------------------------

Main Office Inspection      Next Inspection Date: May 2011

Field      4398 Roger B. Chaffee, Suite 200, Grand Rapids, MI

Temporary Job Site      \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a small engineering firm that employs 25 individuals. The licensee possesses four Troxler 3440 moisture density gauges, for use daily/weekly during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs four authorized gauge users who have completed manufacturers training. The gauges are stored in a locked cabinet in the licensee's facility located at 4398 Roger B. Chaffee, Suite 200, Grand Rapids, Michigan.

**Performance Observations**

At the time of the inspection the gauges were not in use. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. The operator demonstrated an adequate level of understanding of emergency and handling procedures during job-site interviews. Security during transport and at the job-site was described and observed respectively with no problems noted.