NRC FORM 591M PAR (10-2003) 10 CFR 2.201		PECTION PEPORT		J.S. NUCLEAR REGULATO	RY COMMISSION						
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION											
1. LICENSEE/LOCATIO			2. NRC/REGIONAL OFFICE								
Pharmasett, Inc.											
303A College Road East			U.S. Nuclear Regulatory Commission								
Princeton, New Jersey 08540			Region I, 475 Allendale Road								
REPORT Nos 030-3	86980/2006-001		King of Prussia, P	ennsylvania 19406-14	115						
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S	3)	5. DATE(S) OF INSPECTION	ON						
030-36980	,	29-31066-01	,	July 13, 2006							
LICENSEE:				, i, iii							
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X											
	30 days, the actions desc	cribed by me to the inspect	ective Actions for Item or will be taken to correct the v	iolations identified. This state							
			201 (corrective steps aiready to en response to NRC will be red								
Title	,	ted Name	•	gnature	Date						
LICENSEE'S REPRESENTATIVE											
NRC INSPECTOR		nior Health Physicis	st /	RA/	7/13/06						
NRC FORM 591M PART	1 (Rev. by RI 07/06)			E:\Filenet\	ML062010105.wpd						

SUNSI Review Completed By:	/RA/	Betsy Ullrich	х	Public	X	Non-Sensitive
----------------------------	------	---------------	---	--------	---	---------------