



**Docket File Information**  
**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**



1. LICENSEE <b>Regional Medical Imaging</b> REPORT NUMBER(S) <b>2006-001</b>	2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>
--	---

3. DOCKET NUMBER(S) <b>030-31367</b>	4. LICENSE NUMBER(S) <b>21-26076-01</b>	5. DATE(S) OF INSPECTION <b>July 27, 2006</b>
---	--	--

6. INSPECTION PROCEDURES USED <b>87130</b>	7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>
---	---

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>2200</b>	2. PRIORITY <b>3</b>	3. LICENSEE CONTACT <b>Randy Hicks</b>	4. TELEPHONE NUMBER <b>810/732-1919</b>
-----------------------------------	-------------------------	---	--

<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: <b>7/2009</b>
<input type="checkbox"/> Field Office _____	
<input type="checkbox"/> Temporary Job Site _____	

**PROGRAM SCOPE**

Licensee is a small imaging practice located in Flint, Michigan. This licensee uses only unit doses supplied by Cardinal Health. The licensee has two technicians performing patient studies. The licensee sees approximately 15 patients per day at the clinic.

**Performance Observations**

The inspector toured the facility and conducted interviews of the staff. Each appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

The inspector observed the nuclear medicine staff perform injections of radiopharmaceuticals. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no abnormalities were noted.