Plant North

N

0 50 100 Feet

1.2 1.8 2.7 4.0 6.0 8.9 13.2 19.6 29.1 43.3 64.4 95.7 142.4 258.1 467.9 848.4 1538.2

EM-61 Metal Detection Channel D (Weeks 1 - 4)
millivolts

Legend

- Existing Structures
- Former Structures
- Water
- Wetland
- Excavated Water/Electric Lines

Note: White space indicates areas where EM Survey was not conducted.

D-01

Figure 3
EM Survey Results
Peninsula Area Investigation Report
CYAPCO, Haddam Neck Plant
Haddam, Connecticut
MACTEC, Inc.

Prepared by BRP | Checked by NSG

Document: P:\Projects\CYAPCO\2008\Map\Documents\Peninsula_Investigation\AOC13_Mk47_LS.mxd PDF: P:\Projects\CYAPCO\GIS\Figures\Peninsula_Investigation\Figure3.pdf 07/21/2008 10:54 AM brownr