



- Legend**
- Not Excavated
  - ⊞ No Debris Found
  - ⊞ Asbestos Contaminated Material
  - ⊞ No Apparent ACM - Metallic Debris
  - ⊞ DEP Requested Test Pits June 2006
  - Existing Structures
  - Former Structures
  - Water
  - Wetland
  - Excavated Water/Electric Lines
- Note: White space indicates areas where EM Survey was not conducted.

D-02 **Figure 4**  
**Test Pit Locations**  
 Peninsula Area Investigation Report  
 CYAPCO, Haddam Neck Plant  
 Haddam, Connecticut  
 MACTEC, Inc.