



Legend			
○	Not Excavated	■	Post Demo Soil Sample
⊕	No Debris Found	⊕	Monitoring Well
⊕	Asbestos Contaminated Material	⊕	Decommissioned Well
⊕	No Apparent ACM - Metallic Debris	⊕	Production Well
⊕	DEP Requested Test Pits June 2006	⊕	Water
⊕		⊕	Wetland
⊕		⊕	Existing Structures
⊕		⊕	Former Structures
⊕		⊕	Survey Area
⊕		⊕	Area with Asbestos Contaminated Material (ACM)
⊕		⊕	Estimated Excavation Area
⊕		⊕	Excavated Water/Electric Lines
⊕		⊕	Archaeological Site - Approximate Location
⊕		⊕	Test Pit
⊕		⊕	Sediment
⊕		⊕	Surface Water

Note: White space indicates areas where EM Survey was not conducted.

D-03X Figure 5  
 Summary of Findings  
 Peninsula Area Investigation Report  
 CYAPCO, Haddam Neck Plant  
 Haddam, Connecticut  
 MACTEC, Inc.