2 08/22/2006 11:55 FAX 2763288225

A&G COAL CORP

Ø 001



des to the

and the second

A & G Coal Corporation PO Box 1010 Wise, VA 24293 Ph: (276) 328-3421 Fax: (276) 328-8225



Shipping Address: 6250 Hurricane Rd., Wise, VA 24293

FA TO: RON ROLPH Fax #: 610-337-5269 Ext 22 From: _ ()) muc Date: 8-22-06 Pages: _____ (Including Cover Sheet) 1997 - 1999 1997 - 1999 - 1995 Comments: passersat Sec. 1 5.00 · · · · · ·

P. 2 EILE FIGUR TECHNOLOGIES INC. August 11, 2006 A &C Coal Company Job # 9 - Prep Plant Po Box 1010 Wise, VA 24293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Suivey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Rease file all documents in the plant office for future NRC inspections. Please folle all documents in the plant office for future NRC inspections. Sincerely, Mark Mark David Swindell, President, RSO Ce Darrell Grigsby, General Manager A&G Coal Company	2/2006	11:55 FAX 2763288225 A&G COAL C	CORP	Ø 002
August 11, 2004 A &G Coal Company Job # 9 - Prep Plant Po Box 1010 Wise, VA 24293 Ref: Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken! Radiation Survey Performed and documented. Leak Test, Shutter Test, and Physical Liventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Sincerely, Arid Swindell, President, RSO Co Darrell Grigsby, General Manager A&G Coal Company				p.2
August 11, 2004 A &G Coal Company Job # 9 - Prep Plant Po Box 1010 Wise, VA 24293 Ref: Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken! Radiation Survey Performed and documented. Leak Test, Shutter Test, and Physical Liventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Sincerely, Arid Swindell, President, RSO Co Darrell Grigsby, General Manager A&G Coal Company				•
A & G Coal Company Job # 9 - Prep Plant Po Box J010 Wise, VA 24293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATT: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 8. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cer Darrell Grigsby, General Manager A&G Coal Company		ENERGY TECHN	ologies INC.	
A & G Coal Company Job # 9 - Prep Plant Po Box 1010 Wise, VA 224293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 8. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Sincerely, David Swindell, President, RSO Ce. Darroll Grigsby, General Manager A&G Coal Company				
A & G Coal Company Job # 9 - Prep Plant Po Box 1010 Wise, VA 224293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 8. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Sincerely, David Swindell, President, RSO Ce. Darroll Grigsby, General Manager A&G Coal Company		August 11, 2006		
Job # 9 – Prep Plant Po Box 1010 Wise, VA 24293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 5. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sinterely, David Swindell, President, RSO Ce Darrell Grigsby, General Manager A&G Coal Company				
Po Box 1010 Wise, VA 24293 Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) ATTN: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 5. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company				
Ref. Radiation Protection Program Audit (Kay Ray Density Gauge) AT N: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Radiation Survey performed and documented. Radiation Safety Training was provided to site staff NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company	•			
(Kay Ray Density Gauge) AT N: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – Radiation Safety Training was provided to site staff. – Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Ce Darrell Grigsby, General Manager-A&G Coal Company				
(Kay Ray Density Gauge) AT N: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – Radiation Safety Training was provided to site staff. – Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Ce Darrell Grigsby, General Manager A&G Coal Company		D_C D_Jinting D_ Part - Deres Audia	ilad Marco -	
AT N: Darrell Davis, Plant Foreman As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided (Please Post in Plant Office) 5. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Ce Darrell Gnigsby, General Manager A&G Coal Company				
As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) S. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company				
As requested, Energy Technologies Inc. has performed a Radiation Protection Audit at your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) S. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company				
your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager-A&G Coal Company		AIIN: Darrell Davis, Plant Foreman		
your coal preparation plant. The results and deficiency recommendations are attached. The following actions have been taken: Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager-A&G Coal Company				
The results and deficiency recommendations are attached. The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company			formed a Radiation Protection Audit at	
The following actions have been taken Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. – NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager-A&G Coal Company			e attached	
 Radiation Survey performed and documented. Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, M.K. A.M. David Swindell, President, RSO Cc. Darrell Grigsby, General Manager A&G Coal Company 			c quaticu.	
 Leak Test, Shutter Test, and Physical Inventory were performed. Radiation Safety Training was provided to site staff. ~ NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, MK. Automatication Area Signs posted at gauge. David Swindell, President, RSO Cc Darrell Grigsby, General Manager A&G Coal Company 				
 Radiation Safety Training was provided to site staff NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, JAK. Addut David Swindell, President, RSO Cc: Darrell Grigsby, General Manager-A&G Coal Company 				
 4. NRC Form 3 "Notice to Employees" was provided. (Please Post in Plant Office) 5. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, JAK. August David Swindell, President, RSO Cc: Darrell Grigsby, General Manager, A&G Coal Company 				
 5. Radiation Area Signs posted at gauge. Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc. Darrell Grigsby, General Manager-A&G Coal Company 				
Please file all documents in the plant office for future NRC inspections. Please contact us if you have additional needs or questions. Sincerely, David Swindell, President, RSO Cc Darrell Grigsby, General Manager-A&G Coal Company				
Please contact us if you have additional needs or questions. Sincerely, DAK. Add David Swindell, President, RSO Cc. Darrell Grigsby, General Manager A&G Coal Company		5. Radiation Area Signs posted at gaug	(e.	
Sincerely, DAK. AMM David Swindell, President, RSO Cc. Darrell Grigsby, General Manager-A&G Coal Company		Please file all documents in the plant office for	future NRC inspections.	
Sincerely, David Swindell, President, RSO Cc: Darrell Grigsby, General Manager-A&G Coal Company		Please contact us if you have additional needs of	r questions	
David Swindell, President, RSO Cc. Darrell Grigsby, General Manager-A&G Coal Company			, decorona.	
David Swindell, President, RSO Cc. Darrell Grigsby, General Manager-A&G Coal Company				
Cc Darrell Grigsby, General Manager - A&G Coal Company		Sincerely, example and a reading of the second of the seco		
Cc Darrell Grigsby, General Manager - A&G Coal Company		TX IK ANI		
Cc Darrell Grigsby, General Manager - A&G Coal Company		David Swindell President RSO		
			al Company	
		Cel Daron Cingsoy, Cencial Malager Aaco C	Jai Company	
		and the second secon		
			-	
		Delivarios: 8819 Joe Daniels Ro	od; Knoxville, TN 37931	