



UPMC Cardiovascular Institute
at UPMC Passavant North Hills

Part of
University of Pittsburgh
Medical Center

9365 McKnight Road
Suite 700
Pittsburgh, PA 15237
412-367-8202

Passavant Professional
Building
9104 Babcock Boulevard
Suite 4106
Pittsburgh, PA 15237
412-366-2010

3 St. Francis Way
Suite 202
Cranberry Twp, PA 16066
724-772-1133

cviwebmaster@upmc.edu

Saleem Ahmed, MD

Sam A. Buffer, MD, FACC

Mohan Chabra, MD, FACC

Joseph A. Gerard, MD, FACC

Kian Kooros, MD

Sunder Rao, MD, FACC

Lewis B. Rappaport, MD,
FACC

Br. 2

6E:1 PM 27 NOV 2006

RECEIVED
REGION 1

November 20, 2006

Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

RE: Closeout Survey and Wipes RML# 37-25197-01

03032736

Dear Sir or Madam:

Attached are the final wipes and surveys for our facility located at Arcadia Court,
9380 McKnight Road, Suite 201, Pittsburgh, PA 15237.

All sealed sources have been accounted for and are located at our new facility
located at 9365 McKnight Road, Suite 700, Pittsburgh, PA 15237..

All radioactive waste was low level, decayed to below bkg and has been removed.

Please remove 9380 McKnight Road, Suite 201, Pittsburgh, PA 15237 from our
license.

Change our mailing address to 9365 McKnight Road, Suite 700, Pittsburgh, PA 15237.

You may reach me by contacting the practice manager, Elena Pascucci, 412-367-8202
ext 2460.

Sincerely,

Dr. Lewis Rappaport, RSO/EMF

Dr Lewis Rappaport, RSO
UPMC Cardiovascular Institute Passavant at North Hills
9365 McKnight Road, Pittsburgh, PA 15237.

139773

NMSS/RGNI MATERIALS-002

Final Surveys and Wipes

RML: NRC# 37-25197-01
UPMC Cardiovascular Institute Passavant at North Hills
Facility: 9380 McKnight Road, Suite 201

412-367-8202 Ext 2460 Elena Pascucci ,Practice Manager

All waste was decayed to BKG and removed.

Area Surveys: Background 0.03mR/Hr

Ludlum 14C s/n 95903 Ck Source:ok

Camera Area: 0.03 mR/Hr Dose Area: 0.03 mR/Hr Computer Area: 0.03 mR/Hr

Injection Area: 0.03 mR/Hr, Treadmill Area: 0.03 mR/Hr Waiting Room: 0.03 mR/Hr

Hallways: 0.03 mR/Hr, Patient Restroom: 0.03 mR/Hr, Rad Waste Storage Area: 0.03 mR/Hr.

Area Wipes: Caprac Well Counter S/N 150670

**Efficiency used for wipes- 90% or CF 1.1
Bkg: 601 cpm**

Camera Area: 22 dpm

Dose Area: 36 dpm

Computer Area: 17 dpm

Injection Area: 25 dpm

Treadmill Area: 106 dpm

Waiting Room: 14 dpm

Entrance Doorway Floor: 26 dpm,

Hallway Floor: 31 dpm,

Patient Restroom: 36 dpm,

Rad Storage Area: 56 dpm.

All net wipes, no removable contamination which exceeds trigger levels.

Completed By: Donald Ashton CNMT, NCT
Donald Ashton , CNMT, NCT

Nov 17, 2006

This is to acknowledge the receipt of your letter/application dated

11/20/2006, and to inform you that the initial processing which includes an administrative review has been performed.

☒ Ameudment 37-25197-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 139773
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.