



FORM TI-1 CASE RESOLUTION		
Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: <u>705646</u>		
Region: <u>III</u>		
OLD - Complete Name, Address, Contact, Phone Number: Gary Sanitary District Barry Robinson 3500 west 3 rd Avenue Instrument Specialist Gary, IN 46406 219.712.7227		
NEW - Complete Name, Address, Contact, Phone Number:		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) Mr. Robinson informed me that he was aware of two of the gauges and would look around the facility for the other gauges. He was the responsible person that would completed the registration forms.		
Describe Communication with Registration Vendor:		
Vendor Follow-up Action:		
Final Action Taken: Mr. Robinson was designated as the responsible person.		
Cause of Bad Address/Lesson Learned:		

FORM TI-2 DEVICE INFORMATION

RCODE: <u>705646</u>								
ID	Model Number ¹	Serial Number	Isotope	Activity	Sold Date	Vendor	Status (A ² or N ³)	Comments
1	SGH		CS-137	1000		TN Technologie S		
2	5191		"	"		"		
3	"		"	"		"		
4	"		"	"		"		
5	"		"	"		"		
6	"		"	"		"		
7	"		"	"		"		
8	"		"	"		"		
9	"		"	"		"		
10	"		"	"		"		
11	"		"	"		"		
12	"		"	"		"		
13	"		"	"		"		
For additional GLD's received by the licensee identified during the inspection:								

¹Include only registerable gauges identified by Headquarters as "open" cases.

²Accounted for: A device is accounted for if (1) the device is located at the licensee's facility, (2) it has been verified that the device has been transferred to an authorized recipient or properly disposed, or (3) a reasonable assurance has been provided that the device has been transferred to an authorized recipient or properly disposed.

³Not Accounted for: A device is not accounted for if the location of the device is unknown and/or the licensee cannot provide a reasonable assurance that the device has been transferred to an authorized recipient for proper disposal.

FORM TI-2 DEVICE INFORMATION

RCODE: <u>705646</u>								
ID	Model Number ¹	Serial Number	Isotope	Activity	Sold Date	Vendor	Status (A ² or N ³)	Comments
1	SGH		CS-137			TN Technologie s		
2	5191		"			"		
3	"		"			"		
4	"		"			"		
5	"		"			"		
6	"		"			"		
7	"		"			"		
8	"		"			"		
9	"		"			"		
10	"		"			"		
11	"		"			"		
12	"		"			"		
13	"		"			"		
For additional GLD's received by the licensee identified during the inspection:								

¹ Include only registerable gauges identified by Headquarters as "open" cases.

² Accounted for: A device is accounted for if (1) the device is located at the licensee's facility, (2) it has been verified that the device has been transferred to an authorized recipient or properly disposed, or (3) a reasonable assurance has been provided that the device has been transferred to an authorize recipient or properly disposed.

³ Not Accounted for: A device is not accounted for if the location of the device is unknown and/or the licensee cannot provide a reasonable assurance that the device has been transferred to an authorized recipient for proper disposal.

-APPENDIX B

ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

APPENDIX C

FORM TI-3 GENERAL LICENSEE INSPECTION DOCUMENTATION

RCODE: 705646

General Licensee Information:

Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:

Barry Robinson
Same address

Results of inspection: (check the appropriate boxes)

The general licensee of record is located at the address of record and

all GLD are accounted for

not all GLD are accounted for

The general licensee of record is not located at the address of record, however GLD are being used under new ownership at the address of record and

all GLD are accounted for

not all GLD are accounted for

The general licensee of record is not located at the address of record, however they are using GLD at another location and

all GLD are accounted for

not all GLD are accounted for;

Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.

Other: (explain)

Gauge Information:

ID For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge: