

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE CTS REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35058	4. LICENSE NUMBER(S) 34-26271-02	5. DATE(S) OF INSPECTION March 21, 2007	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03225	2. PRIORITY 5	3. LICENSEE CONTACT Willie Cline	4. TELEPHONE NUMBER 740/969-2720
-----------------------------	------------------	-------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 3/12 (3/2012)

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is a gauge training and service provider located in Amanda, Ohio. The licensee provides comprehensive service to gauge users in the repair and calibration of moisture/density gauges. Licensee is also authorized to provide initial training of gauge users. The licensee employees one additional service technician to assist with the workload during peak periods.

Performance Observations

Licensee demonstrated for the inspector the procedure used to receive gauges from clients including the leak testing of clients gauges. Interviews with licensee staff demonstrated an adequate level of knowledge of radiation safety.

Independent surveys of the gauge storage area indicated minimal results. Although licensee personnel are badged, readings for the past year were nominally at the minimum level. No violations of requirements were noted.