

Bartlett Regional Hospital

3260 Hospital Drive • Juneau, Alaska 99801 • Telephone 907-796-8900

April 9, 2007


Bartlett Regional Hospital
3260 Hospital Drive
Juneau, AK 99801

License Number: 50-17686-01

Subject: Treadmill Room Decommissioning

Please find attached the floor plan of the old treadmill room and the survey results. The survey was done by Eric Theis, CNMT. The 10 X12' room was divided into 10 quadrants with each one carefully surveyed using a Ludlum 14C survey meter with a pancake probe. The wipe tests were done using a Captus-600 well counter. No areas of the survey exceeded the background level of 0.03 mR/hr and wipes showed no detectable radiation levels.

Sincerely,



Gordon T. Blair, MD
Radiation Safety Officer

471309

Bartlett Regional Hospital

License No. 50-17686-01

Treadmill Room Survey		Date:	
Survey Results	Bkg .03 mr/hr	Wipe Results	
0.03 mr/hr	Area 1		
0.03 mr/hr	Area 2	0.00 dpm corrected	
0.03 mr/hr	Area 3	0.00 dpm corrected	
0.03 mr/hr	Area 4	0.00 dpm corrected	
0.03 mr/hr	Area 5	0.00 dpm corrected	
0.03 mr/hr	Area 6	0.00 dpm corrected	
0.03 mr/hr	Area 7	0.00 dpm corrected	
0.03 mr/hr	Area 8	0.00 dpm corrected	
0.03 mr/hr	Area 9	0.00 dpm corrected	
0.03 mr/hr	Area 10	0.00 dpm corrected	
Instruments Used			
Surveys		Wipes	
Make	Ludlum	Make	Capintec
Model	14C	Model	Captus-600
Detector Type	Pancake Probe 44-99	Detector Type	Well
Range	0.01 mr/hr to 2000 mr/hr	Range	Minimum detectable counting range is 17 cpm or 0.009 nCi
Calibrate Date	12-20-2006	Calibrate Date	10-12-200

Decommissioned Treadmill Room

