



*Docket File Information*  
**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**



1. LICENSEE <b>Kinnco, Inc</b> REPORT                      2007-001	2. NRC/REGIONAL OFFICE <b>Region III</b>
---	---

3. DOCKET NUMBER(S) 030-19707	4. LICENSE NUMBER(S) 21-21045-01	5. DATE(S) OF INSPECTION June , 2007
----------------------------------	-------------------------------------	---

6. INSPECTION PROCEDURES USED  87124	7. INSPECTION FOCUS AREAS  03.01 - 03.07
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Don Wainmans	4. TELEPHONE NUMBER 231.267.5180
-----------------------------	------------------	-------------------------------------	-------------------------------------

<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: June 2012
<input type="checkbox"/> Field	
<input type="checkbox"/> Temporary Job Site	

**PROGRAM SCOPE**

The licensee is a small piping supply company that employs six individuals. The licensee possesses one NDS Tune Wall Calibrator used during the construction of oil and gas pipeline assemblies. The device had a physical footprint similar to a tractor trailer and was designed to be mobile. The device had not been transported since 1992 and there are no plans to transport the device. The device is stored in a locked cabinet on the device trailer at the licensee's main office in Williamsburg, Michigan. The source is also locked on the Calibrator unit.

**Performance Observations**

The operator toured the facility including the tube wall calibrator. No deficiencies were noted. The inspector noted that the device was locked when not in use. The operator demonstrated an adequate level of understanding of emergency and handling procedures. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

The last inspection, conducted by Chris Martin on May 8, 2002, found no violations.