

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE General Dynamics Land Systems REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-19731	4. LICENSE NUMBER(S) 21-21068-01	5. DATE(S) OF INSPECTION June 7, 2007	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03214	2. PRIORITY 1B5	3. LICENSEE CONTACT Boyd Rose	4. TELEPHONE NUMBER 810/825-5767
------------------------------------	---------------------------	---	--

Main Office Inspection Next Inspection Date: 6/2010 2012

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is a manufacture/distributor of licensed material associated with the muzzle sighting systems of M1A1 tanks. Licensee is located in Sterling Heights, Michigan. The licensee assembles and repairs the main battle tank for the army.

Performance Observations

Licensee demonstrated for the inspector leak test procedures and inventory control procedures. Interviews with licensee staff demonstrated an adequate level of knowledge of radiation safety.

Independent surveys of the service area indicated minimal results. No violations of requirements were noted.

