


1998 Aerial Photograph



- EXPLANATION**
- 1 through 6 Features that are in or Adjacent to Withdrawal Area
 - a through h Features that are Outside the Withdrawal Area
 - - - - - Inferred Linear Feature
 - Normal Fault; Bar and Ball on Downthrown Side.
 - ▭ Disposal Cell Footprint
- Section Numbering within a Township
- | | | | | | |
|----|----|----|----|----|----|
| 6 | 5 | 4 | 3 | 2 | 1 |
| 7 | 8 | 9 | 10 | 11 | 12 |
| 13 | 14 | 15 | 16 | 17 | 18 |
| 19 | 20 | 21 | 22 | 23 | 24 |
| 25 | 26 | 27 | 28 | 29 | 30 |
| 31 | 32 | 33 | 34 | 35 | 36 |

PLATE 1

U.S. DEPARTMENT OF ENERGY GRAND JUNCTION, COLORADO	Work Performed by S.M. Stoller Corporation Under DOE Contract No. DE-AC01-02GJ79491
---	--

Aerial Photography Interpretation
for Crescent Junction Withdrawal Area
and Nearby Surrounding Area

DATE PREPARED: March 28, 2007	FILENAME: X0136200
----------------------------------	-----------------------