



View South

Photo: K. Hanson (June 2006)

Progress Energy Carolinas
<b>Shearon Harris Nuclear Power Plant</b>
<b>Units 2 and 3</b>
<b>Part 2, Final Safety Analysis Report</b>
New Hill, North Carolina
Photograph of Lithofacies II Sandstone and Siltstone Exposed in the Emergency Service Water Discharge Channel at the HNP Site
FIGURE 2.5.1-234