



Source: Wooten et al. (2001)

Progress Energy Carolinas  
**Shearon Harris Nuclear Power Plant  
 Units 2 and 3  
 Part 2, Final Safety Analysis Report**  
 New Hill, North Carolina

Schematic Block Diagram and  
 Map Showing Structural Relations  
 for Faults in the Site Area

FIGURE 2.5.1-236

Rev. 0