U.S. HIGHWAY 191

HIGHWAY 191
PHASE 2 REMEDIATION

MK

V-ML-117

V-ML-194

V-ML-194

ML

R0019

CARETAKER
RESIDENCE

INTERIM MILLSITE
REMEDIAL ACTION
PROJECT

R0018

COURTHOUSE WASH

LL

R0020

LK

MAIN RESIDENCE

R0016

R0017

R0014

R0013

R0015

R0009

R0008

R0007

R0006

R0005

R0003

R0004

R0010

R0001

R0002

SUPPLEMENTAL
STANDARDS

R0011

R0012

V-KK-073

R0027

R0028

UTILITY
CORRIDOR

R0026

R0025

LANDFILL
AND POND

KK

COLORADO RIVER

KL

V-KK-073

R0027

R0026

LEGEND

- DOE Site Boundary
- Project Boundary
- Adjacent Projects
- Supplemental Standards
- Verification Grid
- Verification Blocks
- Building
- River
- Drainage
- Paved Road
- Gravel Road
- Dirt Road
- Underground Gas Line
- Underground Gas Line Easement
- Radiological Assessment Locations

Depth of Assessed Contamination

- 0 in.
- 6 in.
- 12 in.
- 18 in.

N

SCALE IN FEET

60 30 0 60

U.S. DEPARTMENT OF ENERGY
GRAND JUNCTION, COLORADO

Work Performed by
S.M. Stoller Corporation
Under DOE Contract
No. DE-AC01-02GJ79491

Plate 1
Verification Grid for VP018 (McClatchy Property)
Showing Depth of Assessed Contamination

DATE PREPARED: September 20, 2003

FILENAME: X0227300

N:\MOA\999\0009\03\X02273\X0227300.mxd coatesc 9/20/2007 10:48:48 AM

D-01