DOE SITE BOUNDARY

SUPPLEMENTAL STANDARDS AREA TWO

SUPPLEMENTAL STANDARDS AREA ONE

DRAINAGE (NOT BACKFILLED)

HIGHWAY 279

COLORADO RIVER

EF | EG | EH | EI

DF | DG | DH | DI

CF | CG | CH | CI

LEGEND

- DOE Site Boundary
- Project Boundary
- Supplemental Standards
- Backfill
- Excavation
- Verification Grid
- Verification Blocks
- Drainage (Not Backfilled)
- Radiological Assessment Locations

Depth of Assessed Contamination

- 0 in.
- 6 in.
- 12 in.
- 24 in.
- 36 in.
- Inaccessible Area

N

SCALE IN FEET

70 35 0 70

U.S. DEPARTMENT OF ENERGY GRAND JUNCTION, COLORADO	Work Performed by S.M. Stoller Corporation Under DOE Contract No. DE-AC01-02GJ79491

Plate 1
Verification Grid for VP019 (Policaro Property)
Showing Depth of Assessed Contamination

DATE PREPARED:	FILENAME:
September 18, 2003	X0226400

D-01