

**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**



1. LICENSEE <b>Subbarao Chavali, M.D.</b> REPORT NUMBER(S) <b>2008-001</b>	2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>
--	---

3. DOCKET NUMBER(S) <b>030-37412</b>	4. LICENSE NUMBER(S) <b>21-32644-01</b>	5. DATE(S) OF INSPECTION <b>3/27/08</b>
---	--	--

6. INSPECTION PROCEDURES USED <b>87130</b>	7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>
---	---

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>2121</b>	2. PRIORITY <b>5</b>	3. LICENSEE CONTACT <b>Ray Carlson</b>	4. TELEPHONE NUMBER <b>734/395-73616600</b>
-----------------------------------	-------------------------	---	--

Main Office Inspection      Next Inspection Date: 3/2013

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

Licensee is the medical clinic located in Bay City, Michigan. Licensee has a small nuclear medicine program conducting routine diagnostic imaging procedures. The licensee has one tech who performs approximately 7 procedures per day. This clinic receives its radiopharmaceuticals in the form of unit doses from Cardinal Pharmacy.

**Performance Observations**

The inspector toured the facilities and interviewed authorized users and staff members. Each appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

The inspector observed the nuclear medicine staff perform injections of radiopharmaceuticals. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no abnormalities were noted.

