

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

RMT, Inc.
Madison, WI

REPORT NUMBER(S) 2008-001

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351

3. DOCKET NUMBER(S)

030-20618

4. LICENSEE NUMBER(S)

48-21408-01

5. DATE(S) OF INSPECTION

4/8/08

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name


Signature

Date

LICENSEE'S
REPRESENTATIVE

NRC INSPECTOR

Michael M LaFrance



4/8/08

SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE RMT, Inc REPORT NUMBER(S) 2008-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-20618	4. LICENSE NUMBER(S) 48-21408-01	5. DATE(S) OF INSPECTION 4/8/2008	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 3.01-.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT John Hanson	4. TELEPHONE NUMBER 608-831-4444
----------------------------	------------------	------------------------------------	-------------------------------------

☒

Main Office Inspection

Next Inspection Date: 4/2013

☐

Field Office

☐Temporary Job Site
Inspection

PROGRAM SCOPE

The licensee is a medium sized engineering firm located in the city of Madison, Wisconsin. The licensee has 11 Troxler gauges used for soil density measurements at road projects. The licensee does not perform any service or maintenance activities on the gauges regarding the sources. At the time of the inspection, the licensee employed 40 individuals that had manufacturer training.

Performance Observations

The inspector interviewed a selected number of staff involved in licensed operations including the RSO and gauge users. Each individual had adequate knowledge to ensure the safe use of the devices. The inspector verified that dosimetry was used in the field and that the operators were aware of emergency procedures. The inspector reviewed dosimetry records, inventory and leak test records and training records; no abnormal issues were identified.