



# NRC NEWS

U.S. NUCLEAR REGULATORY COMMISSION

Office of Public Affairs Region IV  
612 E. Lamar Blvd., Suite 400  
Arlington, TX 76011-4125  
Telephone: (817) 860-8128

---

No. IV-08-021  
Contact: Victor Dricks  
Phone: (817) 860-8128

May 20, 2008  
E-Mail: opa4@nrc.gov

## **NRC TO DISCUSS 2007 PERFORMANCE ASSESSMENT FOR COMANCHE PEAK NUCLEAR PLANT**

The Nuclear Regulatory Commission staff will meet in Glen Rose, Texas, on June 5, with representatives of TXU Power, to discuss the agency's assessment of safety performance for last year at the Comanche Peak nuclear plant.

The meeting, which will be open to the public, is scheduled to begin at 6 p.m. at the Somervell County Expo Center, 202 Bo Gibbs Blvd., Glen Rose.

In addition to the performance assessment, the NRC staff will be available to answer questions from the public on the safety performance of Comanche Peak, as well as the NRC's role in ensuring safe plant operation.

"The NRC continually reviews the performance of Comanche Peak and the nation's other commercial nuclear power facilities," NRC Region IV Administrator Elmo E. Collins said. "This meeting will provide an opportunity for a discussion of our annual assessment of safety performance with the company and with local officials and residents who live near the plant."

A letter sent from the NRC Region IV office to plant officials addresses the performance of the plant during 2007 and will serve as the basis for the meeting discussion. It is available on the NRC web site at:

[http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/LETTERS/cp\\_2007q4.pdf](http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/LETTERS/cp_2007q4.pdf).

The NRC utilizes color-coded inspection findings and performance indicators to assess nuclear power plant performance. The colors start with "green" and then increase to "white," "yellow" or "red," commensurate with the safety significance of the issues involved.

The NRC said Comanche Peak operated safely during 2007. However, because of a "white" finding associated with the failure of an emergency diesel generator to start during a

monthly test, a supplemental inspection will be conducted later this year to verify that corrective actions are adequate to prevent recurrence.

Routine inspections are performed by two NRC Resident Inspectors assigned to the plant and by inspection specialists from the Region IV Office in Arlington, Texas.

Current performance information for Comanche Peak Unit 1 is available on the NRC web site at: [http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/CP1/cp1\\_chart.html](http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/CP1/cp1_chart.html) . Current performance information for Comanche Peak Unit 2 is available at: [http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/CP2/cp2\\_chart.html](http://www.nrc.gov/NRR/OVERSIGHT/ASSESS/CP2/cp2_chart.html) .

###

NRC news releases are available through a free list serve subscription at the following Web address: <http://www.nrc.gov/public-involve/listserver.html> . The NRC homepage at [www.nrc.gov](http://www.nrc.gov) also offers a SUBSCRIBE link. E-mail notifications are sent to subscribers when news releases are posted to NRC's Web site.