

From: Keenan Remele [KRemele@kakivik.com]
Sent: Monday, June 30, 2008 3:23 PM
To: James Montgomery
Subject: Question Response
Attachments: Exposure Wipe Testws.PDF; Vault Wipe Tests.PDF

Mr. Montgomery,

Please find attached the wipe test results for the exposure devices and the vaults assigned to the Fairbanks and Valdez locations.

Response to questions:

- #1 – The readings shown were obtained by calculations.
- #2 – No, radiography will not be performed at the Rawlins location.
- #4 – The location noted on the Material License is correct for Valdez. I was going off a drawing that listed an incorrect address.

I hope this answers your questions. If there are more please contact me.

Keenan E. Remele
RSO
Kakivik Asset Management
111 W. 16th Ave, Suite 100
Anchorage, Alaska 99501

Direct: 907.770.9421
Cell: 907.632.7305
Office: 907.770.9400
Fax: 907.770.9450

E-mail Properties

Mail Envelope Properties (85FC18CBF641644CA1EFFF690F06D38D743969)

Subject: Question Response
Sent Date: 6/30/2008 3:22:51 PM
Received Date: 6/30/2008 3:22:51 PM
From: Keenan Remele

Created By: KRemele@kakivik.com

Recipients:
James.Montgomery@nrc.gov (James Montgomery)
Tracking Status: None

Post Office:
kakivik01.kakivik.com

Files	Size	Date & Time
-------	------	-------------

MESSAGE 381110 6/30/2008
Exposure Wipe Testws.PDF 170781
Vault Wipe Tests.PDF 202788

Options

Expiration Date:

Priority: olImportanceNormal

ReplyRequested: False

Return Notification: False

Sensitivity: olNormal

Recipients received: