



CAMECO RESOURCES
Smith Ranch-Highland
Operation
Mail:
P.O. Box 1210
Glenrock, WY
82637 USA

June 11, 2008

Mr. Lowell Spackman, District I Supervisor
Land Quality Division
Wyoming Department of Environmental Quality
122 West 25th Street
Cheyenne, WY 82002

Tel: (307) 358-6541
Fax: (307) 358-4533
www.cameco.com

RE: Permit to Mine 633 and 603, License SUA-1548, Docket 40-8964
Missed Mechanical Integrity Test

Dear Mr. Spackman:

Cameco Resources is herein providing the status of seventeen (17) wells recently discovered missed during our five year Mechanical Integrity Test (MIT). Incorrect data entry resulted in the failure to test the wells within the required time. Subsequently, the wells have been tested and the present status is listed below. The data base has been thoroughly reviewed to ensure accuracy, completeness and confidence of the information in the future.

Well #	MIT DATE	STATUS	ABANDONMENT
CI-125	04/23/08	Failed	Scheduled for abandonment
CI-126	04/24/08	Passed	
CI-127	04/23/08	Passed	
CI-128	04/23/08	Passed	
CI-131	04/23/08	Passed	
CI-132	04/23/08	Passed	
DP-0461	04/25/08	Passed	
EI-312	04/24/08	Passed	
EI-313	04/24/08	Passed	
EI-316	04/24/08	Passed	
2I-170	04/16/08	Passed	
2I-179	04/16/08	Passed	
2I-204	04/16/08	Passed	
3P-026A	05/13/08	Passed	
4P-062A	05/14/08	Passed	

In addition, two (2) wells were missed due to adverse weather conditions. Wells 2P-079 and 2P-085 were tested on 06/06/08 and both passed the integrity test.

Corrective Actions: The MIT data base has been reviewed by three individuals to insure integrity and completeness.

If you have any questions or need additional information please call me at (307) 358-6541, ext. 46.

Sincerely,



John McCarthy
Manager, Environment, Health and Safety, RSO

Cc: D. Mandeville, NRC Project Manager C. Foldenauer T. Cannon
M. D. Bryson S. Bakken File SR-4.3.3.1