

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE BBC & M Engineering REPORT NUMBER(S) 2008-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-36155	4. LICENSE NUMBER(S) 34-32430-01	5. DATE(S) OF INSPECTION July 23, 2008	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Kristy Walsh	4. TELEPHONE NUMBER 513/771-8471
-----------------------------	------------------	-------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 7/2013

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is a civil engineering firm located in Cincinnati, Ohio. They perform soil density and asphalt testing in Ohio, Michigan, Indiana and West Virginia. The licensee has two Troxler 3440 series gauges. The gauges are normally stored at licensee's facility or at the project office for temporary job sites. For use at temporary job sites, the gauges are stored in locked construction trailers and additionally secured to meet the requirements of the two barriers rule. The licensee does not performed any service or maintenance activities on the gauges. The licensee employees four gauge users who have completed the manufacturers training.

Performance Observations

Licensee described procedures used at a temporary jobsite since no such jobsite was available at the time of this inspection. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
B&M Engineering, Inc
11699 Chesterdale Rd
Cincinnati, Oh 45246
REPORT NUMBER(S) 2008001

2. NRC/REGIONAL OFFICE
REGION III
US NUCLEAR REGULATORY COMMISSION
2443 WARRENVILLE ROAD
LISLE IL 60532

3. DOCKET NUMBER(S)
030-36155

4. LICENSE NUMBER(S)
34-32430-01

5. DATE(S) OF INSPECTION
July 23, 2008

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	G. Parker		7/23/08