



- ◆— 10/16/2007
- 10/18/2007
- ▲— 10/19/2007
- ◆— 11/15/2007
- 11/19/2007

Progress Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 3, Environmental Report

Salinity Pattern at 0.15 Meter Depth

FIGURE 2.4-12

Rev 0