

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

| | | | |
|--|---|--|--|
| 1. LICENSEE Paradigm Design, Inc.. REPORT NUMBER(S) 2008-001 | | 2. NRC/REGIONAL OFFICE * Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532 | |
| 3. DOCKET NUMBER(S) 03036188 | 4. LICENSE NUMBER(S) 21-32437-01 | 5. DATE(S) OF INSPECTION July 31, 2008 | |
| 6. INSPECTION PROCEDURES USED 87124 (11/25/03) | 7. INSPECTION FOCUS AREAS 03.01-03.07 | | |

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|------------------------------------|-------------------------|---|--|
| 1. PROGRAM CODE(S) 03121 | 2. PRIORITY 5 | 3. LICENSEE CONTACT Brian Holleman, RSO | 4. TELEPHONE NUMBER 616-785-5581 |
|------------------------------------|-------------------------|---|--|

Main Office Inspection Next Inspection Date: **July 2013**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is authorized to possess and use portable moisture density gauges at temporary job sites anywhere in the United States where the NRC maintains regulatory jurisdiction. The license has 4 employees qualified to use portable moisture gauges at temporary jobsites in Michigan. Each gauge is used frequently during construction season and is stored occasionally at a temporary job site. At the time of the inspection, one gauge was being used at a Michigan temporary job site, but too far from Grand Rapids to travel for an inspection.

Performance Observations

During the inspection, the inspector reviewed and discussed with the RSO: (1) Two tangible barriers required for gauge security and padlocks; (2) DOT requirements; (3) refresher training for gauge users; (4) dosimetry and records; (5) leak tests and inventories; (6) security of licensed material at a temporary job site; (7) survey meter availability; and (8) emergency procedures.