

DAILY QUALITY CONTROL REPORT
New Haven Depot Characterization – Project No. 06-3070.02 Task 20

This field report shall be completed each day that field activities are performed at the New Haven Site. Attach an additional sheet of paper, if necessary, to adequately complete each required entry.

<p>JMC PM: <u>Bill Metcalf</u></p> <p>Cabrera PM: <u>John Eberlin</u></p>	<p>Precipitation: <u>Rain all day</u></p> <p>Wind: <u>From the east 10 mph</u></p> <p>Temperature: <u>High 47, low 34</u></p>
---	--

SUBCONTRACTORS ON SITE (Identify subcontractors onsite by company name):

N/A

WORK PERFORMED (Briefly describe project tasks that were performed. Reference appropriate logs if details necessary)

Greg B., Joe W. and Dave K. investigated warehouses to come up with sampling plan. Drove Joe to airport at 9:30 AM. Returned to site, Greg and Dave started floor survey in Bldg 213. Dave surveyed Bldg 215 while Greg shipped off samples and data CD.

PROJECT SCHEDULE (Describe impact of day's work, if any, on overall project schedule):

Tasks 1,2, and 4 are complete. Remainder of bias samples sent offsite today (task 3). On schedule or ahead of schedule as of now.

PROBLEMS, NON-CONFORMANCES, CORRECTIVE ACTIONS, NOTIFICATIONS (Describe any hazards, injuries, regulatory or procedural issues, items of non-compliance, etc. Identify individuals contacted as a result of these items. Include name/title/organization/time contacted/and a summary of content of discussion):

Rained all day and could not complete walkovers or soil samples. Will continue both on Monday.

SITE VISITORS, CONTACTS (Identify any non-project personnel that visited the site or made contact with project personnel. Include names/titles/organizations/time of contact/ and any other pertinent details of the conversation):

DQCR prepared by:

Print Name	Signature	Title
Greg Bright		Field Site Manager

DAILY QUALITY CONTROL REPORT
New Haven Depot Characterization – Project No. 06-3070.02 Task 20

This field report shall be completed each day that field activities are performed at the New Haven Site. Attach an additional sheet of paper, if necessary, to adequately complete each required entry.

JMC PM: Bill Metcalf _____ **Precipitation:** N/A _____
Cabrera PM: John Eberlin _____ **Wind:** From the east 5 mph _____
 _____ **Temperature:** High 60, low 45 _____

SUBCONTRACTORS ON SITE (Identify subcontractors onsite by company name):

Ian Harris and Bill Gardener

WORK PERFORMED (Briefly describe project tasks that were performed. Reference appropriate logs if details necessary)

Derrick A and Ian H. scan walls in 211, while Bill G., and Dave K. scan walls in 212. After they finish those surveys, both teams start surveying in Building 213. Greg B. enters data into data sheets and counts smears.

PROJECT SCHEDULE (Describe impact of day's work, if any, on overall project schedule):

Tasks 1-5 and 13 are complete. Task 14 is nearly complete, just building surveys are needed. Now focusing on scans in warehouses.

PROBLEMS, NON-CONFORMANCES, CORRECTIVE ACTIONS, NOTIFICATIONS (Describe any hazards, injuries, regulatory or procedural issues, items of non-compliance, etc. Identify individuals contacted as a result of these items. Include name/title/organization/time contacted/and a summary of content of discussion):

Heard from Airgas that smaller tanks of P-10 gas are coming tomorrow.

SITE VISITORS, CONTACTS (Identify any non-project personnel that visited the site or made contact with project personnel. Include names/titles/organizations/time of contact/ and any other pertinent details of the conversation):

DQCR prepared by:

Print Name	Signature	Title
Greg Bright		Field Site Manager

DAILY QUALITY CONTROL REPORT
New Haven Depot Characterization – Project No. 06-3070.02 Task 20

This field report shall be completed each day that field activities are performed at the New Haven Site. Attach an additional sheet of paper, if necessary, to adequately complete each required entry.

JMC PM: Bill Metcalf _____ **Precipitation:** N/A _____
Cabrera PM: John Eberlin _____ **Wind:** From the east 5 mph _____
 _____ **Temperature:** High 60, low 45 _____

SUBCONTRACTORS ON SITE (Identify subcontractors onsite by company name):

Ian Harris and Bill Gardener

WORK PERFORMED (Briefly describe project tasks that were performed. Reference appropriate logs if details necessary)

Derrick A and Ian H. scan walls in 213 Section 4, while Bill G., and Dave K. scan walls in 213 Section 1, until 213 scans are completed. Dave K. and Bill G. begin biased measurements on overhead columns in 215. With 1 floor monitor delivered today, Derrick and Ian start floor scans in 215.

PROJECT SCHEDULE (Describe impact of day's work, if any, on overall project schedule):

Tasks 1-5 and 13 are complete. Task 14 is nearly complete, just building surveys are needed. Now focusing on scans in warehouses.

PROBLEMS, NON-CONFORMANCES, CORRECTIVE ACTIONS, NOTIFICATIONS (Describe any hazards, injuries, regulatory or procedural issues, items of non-compliance, etc. Identify individuals contacted as a result of these items. Include name/title/organization/time contacted/and a summary of content of discussion):

N/A

SITE VISITORS, CONTACTS (Identify any non-project personnel that visited the site or made contact with project personnel. Include names/titles/organizations/time of contact/ and any other pertinent details of the conversation):

N/A

DQCR prepared by:

Print Name	Signature	Title
Greg Bright		Field Site Manager

DAILY QUALITY CONTROL REPORT

New Haven Depot Characterization – Project No. 06-3070.02 Task 20

This field report shall be completed each day that field activities are performed at the New Haven Site. Attach an additional sheet of paper, if necessary, to adequately complete each required entry.

JMC PM: Bill Metcalf _____ **Precipitation:** N/A _____

Cabrera PM: John Eberlin _____ **Wind:** From the east 5 mph _____

_____ **Temperature:** High 4, low 30 _____

SUBCONTRACTORS ON SITE (Identify subcontractors onsite by company name):

Ian Harris and Bill Gardener

WORK PERFORMED (Briefly describe project tasks that were performed. Reference appropriate logs if details necessary)

Dave K. and Bill G. perform biased measurements on overhead columns in 212, 211, and 213. Ian continues floor scans in 215. Nick Berliner performed static/smears on walls from 0-6 feet in 212 and 215. Greg B. continued counting smears and doing the calibration on the second floor monitor that arrived today.

PROJECT SCHEDULE (Describe impact of day's work, if any, on overall project schedule):

Tasks 1-5 and 13 are complete. Task 14 is nearly complete, just building surveys are needed. Now focusing on scans in warehouses.

PROBLEMS, NON-CONFORMANCES, CORRECTIVE ACTIONS, NOTIFICATIONS (Describe any hazards, injuries, regulatory or procedural issues, items of non-compliance, etc. Identify individuals contacted as a result of these items. Include name/title/organization/time contacted/and a summary of content of discussion):

N/A

SITE VISITORS, CONTACTS (Identify any non-project personnel that visited the site or made contact with project personnel. Include names/titles/organizations/time of contact/ and any other pertinent details of the conversation):

N/A

DQCR prepared by:

Print Name	Signature	Title
Greg Bright		Field Site Manager

DAILY QUALITY CONTROL REPORT
New Haven Depot Characterization – Project No. 06-3070.02 Task 20

This field report shall be completed each day that field activities are performed at the New Haven Site. Attach an additional sheet of paper, if necessary, to adequately complete each required entry.

<p>JMC PM: <u>Bill Metcalf</u></p> <p>Cabrera PM: <u>John Eberlin</u></p>	<p>Precipitation: <u>Overcast</u></p> <p>Wind: <u>From the east 5 mph</u></p> <p>Temperature: <u>High 50, low 28</u></p>
---	---

SUBCONTRACTORS ON SITE (Identify subcontractors onsite by company name):

None

WORK PERFORMED (Briefly describe project tasks that were performed. Reference appropriate logs if details necessary)

Ian H. and Greg B. onsite. Count smears and prepare Cabrera equipment for shipment.

PROJECT SCHEDULE (Describe impact of day's work, if any, on overall project schedule):

All tasks completed except Building 210 and 214 surveys, which will be completed in the Spring.

PROBLEMS, NON-CONFORMANCES, CORRECTIVE ACTIONS, NOTIFICATIONS (Describe any hazards, injuries, regulatory or procedural issues, items of non-compliance, etc. Identify individuals contacted as a result of these items. Include name/title/organization/time contacted/and a summary of content of discussion):

SITE VISITORS, CONTACTS (Identify any non-project personnel that visited the site or made contact with project personnel. Include names/titles/organizations/time of contact/ and any other pertinent details of the conversation):

N/A

DQCR prepared by:

Print Name	Signature	Title
Greg Bright		Field Site Manager

