

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION



1. LICENSEE ABNA Engineering, Inc..		2. NRC/REGIONAL OFFICE Region III	
REPORT NUMBER(S) 2008-001		2443 Warrenville Road, Suite 210	
3. DOCKET NUMBER(S) 03036087		4. LICENSE NUMBER(S) 24-32415-01	5. DATE(S) OF INSPECTION September 25, 2008
6. INSPECTION PROCEDURES USED 87124 (11/25/03)		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Ray Bailey, RSO	4. TELEPHONE NUMBER 314-454-0222
------------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: **September 2013**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is authorized to possess and use CPN portable moisture density gauges at temporary job sites anywhere in the United States where the NRC maintains regulatory jurisdiction. The licensee also possesses one Siemens Ra-226 gauge which is considered "in storage." The gauges are used only in the St. Louis, MO vicinity and are not stored at temporary job sites or at an employee's residence overnight. At the time of the inspection, none of the gauges were being used at a temporary job site and were stored with two tangible barriers.

Performance Observations

During the inspection, the inspector reviewed and discussed with the staff: (1) Two tangible barriers required for gauge security and padlocks while outside the storage area; (2) DOT requirements, hazmat recertification and tests; (3) refresher training for gauge users; (4) dosimetry and records; (5) leak tests and inventories; (6) security of licensed material at each authorized storage facility; (7) survey meter availability; and (8) emergency procedures.